

LAPTOPS ON A EU PALLET



1

Define the center of the carton by drawing two lines, one crossing the other and place the laptops so they align with the back towards center line facing the side of the pallet.


(Carton is a protective layer for the laptops against dirt and dust.)



2

Place the laptops back-to-back and front-to-front.

NOTE: In order to avoid damage during transport, please place the devices mini-mum 20 cm from the edges of the pallet.



Batteries **MUST** be contained inside the machines when transported.
Swollen or non-functioning batteries are not allowed to be part of the shipment. Please remove before shipping.



3

In the next layer place the laptops with screens down. In the third layer the laptops should be placed bottom-to-bottom. Repeat the same procedure until 10th layer.



4

Cover the laptops with bubble wrap, and fix with tape.




Be careful not to tape over the stickers on the devices. If Windows license sticker is damaged, it could lower the value.



5

Isolate the pallet with black protective cover. Attach the KO-number and UN 3481 on all sides.



Load maximum 10 layers to avoid weight damaging the bottom layers.



UN 3481

Download the sign here

